




LOUISIANA
POWER & LIGHT

WATERFORD 3 SES • P.O. BOX B • KILLONA, LA 70066

September 14, 1984

W3P84-2547
Q-3-A35.07.108
3-A1.01.04

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012



REFERENCE: LP&L Letter W3K84-2033 dated August 30, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 108
"Potential Failure to Comply with FSAR Safe Shutdown Commitment"
Fifth Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on September 14, 1984.

At the present time, verification is ongoing and is scheduled to be completed by the end of September, 1984. The Final Report is scheduled to be submitted to the USNRC on September 28, 1984.

Very truly yours,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/TJG/ss

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

IE-27

1/0

8409270835 840914
PDP ADOCK - 000382
S PDR

Mr. John T. Collins
W3P84-2547
Page 2

cc: Director
Office of Management
Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E.L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Mr. W.M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W.A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814