



MIDDLE SOUTH  
UTILITIES SYSTEM

**LOUISIANA**  
POWER & LIGHT

142 DELARONDE STREET  
NEW ORLEANS, LOUISIANA


• P.O. BOX 8008  
70174-8008

• (504) 388-2345

September 14, 1984

W3P84-2552  
Q-3-A35.07.114  
3-A1.01.04

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76012



REFERENCE: LP&L letter W3K84-2055 dated August 31, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 114  
"Possible Damage to Safety Related Equipment Due to Water Hammers"  
Third Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on September 14, 1984.

At the present time, verification of the corrective action is scheduled to be completed in mid September, 1984. The Final Report is scheduled to be submitted to the USNRC on September 21, 1984.

Very truly yours,

R.W. Cook

Nuclear Support & Licensing Manager

KWC/TJG/ss

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

IX-27

8409270837 840914  
PDR ADOCK 05000382  
PDR

1/0

Mr. John T. Collins  
W3P84-2552  
September 14, 1984  
Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M. Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814