

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

BLRD-50-438/84-14
BLRD-50-439/84-13

85 MAR 6 A 7:40 March 1, 1985

U.S. Nuclear Regulatory Commission
Region II
Attn: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - ADAPTOR KEYWAY ON 8-INCH BORG-
WARNER GLOBE VALVES - BLRD-50-438/84-14, BLRD-50-439/84-13 - SECOND
SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector P. E. Fredrickson on January 31, 1984 in accordance with 10 CFR 50.55(e) as NCR 2787. This was followed by our interim reports dated February 29 and July 10, 1984, our final report dated October 25, 1984, and our first supplemental report dated January 4, 1985. Below is our second supplemental report. We consider 10 CFR Part 21 applicable to this deficiency.

As discussed with Inspector A. Ignatonis on February 16, 1985, the date of March 16, 1985 for completion of corrective actions indicated in our first supplemental final report on this matter will not be met. While the work on unit 1 valves has been completed, the work required to meet this commitment for unit 2 has been rescheduled to reflect the change in the overall unit 2 schedule. The corrective action on this matter will be completed by September 26, 1987 for unit 2.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Domes
for J. W. Hufham, Manager
Licensing and Regulations

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8503190390 850301
PDR ADOCK 05000438
S PDR

An Equal Opportunity Employer

IE22
OFFICIAL COPY