

Southern California Edison Company

SCE

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

J. G. HAYNES
STATION MANAGER

TELEPHONE
(714) 492-7700

March 12, 1985

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-361
Licensee Event Report No. 84-079, Revision 1
San Onofre Nuclear Generating Station, Unit 2

Reference: Letter, J. G. Haynes (SCE) to USNRC Document Control Desk,
dated January 25, 1985, Licensee Event Report No. 84-079

The referenced letter provided the required 30-day Licensee Event Report (LER) on deficiencies identified during the routine 18-month snubber surveillance. We have enclosed LER 84-079, Revision 1. It is being submitted to summarize the results of the engineering evaluations for all deficient snubbers and the corrective actions being taken to preclude recurrence.

If you require any additional information, please so advise.

Sincerely,

RWKruiger for JG Haynes

Enclosure: LER No. 84-079, Revision 1

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

J. B. Martin (Regional Administrator, USNRC Region V)

Institute of Nuclear Power Operations (INPO)

8503250163 850312
PDR ADOCK 05000361
S PDR

IE22
11