



NIAGARA MOHAWK POWER CORPORATION / 300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202 / TELEPHONE (315) 474-1511

February 12, 1985
(NMP2L 0340)

Mr. R. W. Starostecki, Director
U. S. Nuclear Regulatory Commission
Region I
Division of Project and Resident Programs
631 Park Avenue
King of Prussia, PA 19406

Re: Nine Mile Point - Unit 2
Docket No. 50-410

Dear Mr. Starostecki:

In our letter of June 29, 1984, we submitted a final report in accordance with 10CFR50.55(e) on a problem concerning actuators furnished by G. H. Bettis (#84-00-02). As part of the corrective action, we committed to replace seals and use Dow Corning Molykote 44 lubricant.

We would like to amend the corrective action to allow the performance of actuator stroke time tests in accordance with the G. H. Bettis' recommendation. Any actuators that fail the test will be modified as originally stated. Corrective action should be completed by June 28, 1985.

Very truly yours,

C. V. Mangan
Vice President
Nuclear Engineering and Licensing

CVM/GG:csb
(0726H)

xc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

R. A. Gramm, NRC Resident Inspector
Project File (2)

8503280360 850212
PDR ADDCK 05000410
S PDR

1/0 1E27