

TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER * 400 NORTH OLIVE STREET, L.B. 81 * DALLAS, TEXAS 75201

BILLY R. CLEMENTS
VICE PRESIDENT, NUCLEAR OPERATIONS

November 19, 1984
TXX-4363

Mr. D.R. Hunter, Chief
Reactor Project Branch 2
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

Docket Nos.: 50-445
50-446

COMANCHE PEAK STEAM ELECTRIC STATION
ITT BARTON PRESSURE SWITCHES
QA FILE: CP-84-32, SDAR-158
FILE NO.: 10110

Dear Mr. Hunter:

On October 23, 1984 we verbally notified your Mr. J. Cummins of a deficiency regarding some differential pressure switches which experience set point shifts in excess of specification requirements when operated at temperatures in excess of 225°F.

We have completed our investigation and concluded that the matter is not reportable under 10CFR50.55(e). Records supporting this determination are available for your inspector's review at the CPSES site.

Very truly yours,

Billy R. Clements

BRC:tlg

cc: NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8412050235 841119
PDR ADOCK 05000445
S PDR