



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 409 838 6631


March 15, 1985

RBG- 20434

File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Martin:



River Bend Station Unit 1
Docket No. 50-458
Final Report/DR-210

Gulf States Utilities Company (GSU) has completed its evaluation of DR-210 concerning bowed circuit board retaining parts in Model 510 DU Rosemount card files. Examination revealed that the card files will perform their intended safety function. GSU has therefore determined this condition is not reportable under 10CFR50.55(e). However, the effected cards are being replaced or reworked and support brackets added to the card files in accordance with Field Deviation Disposition Request Nos. LD1-912 Revision 0, LD1-1668 Revision 0 and 1, and LD1-1716 Revision 0.

Sincerely,

J. E. Booker

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

WMA
JEB/PJD/lp

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8564
8504030079 850315
PDR ADCK 05000458
S PDR

IE-27
10