



Duane Arnold Energy Center
3277 DAEC Road
Palo, IA 52324
Telephone 319 851 7611
Fax 319 851 7611

February 2, 1996
NG-96-0120

Mr. William T. Russell, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-37
Washington, DC 20555-0001

Subject: Duane Arnold Energy Center
Docket No: 50-331
Op. License No: DPR-49
1995 Safety and Relief Valve Failures and Challenges

File: A-118e

Dear Mr. Russell:

In accordance with the requirements of the Duane Arnold Energy Center (DAEC) Technical Specifications (Section 6.11.1.e) and NUREG-0737 (Item II.K.3.3), we wish to inform you that no safety valve or safety relief valve failures or challenges occurred during the calendar year 1995. Please contact this office if you have any questions regarding this matter.

This letter contains no new commitments, nor does it modify any previous commitments.

Sincerely,

A handwritten signature in cursive script that reads "Paul Bessette".

Paul M. Bessette
Manager, Nuclear Licensing

9602120077 960202
PDR ADDCK 05000331
P PDR

120013

ADD31/0

Mr. William T. Russell

NG-96-0120

February 2, 1996

Page 2

PMB/LBS

N:\Iowa\Licensing\NG-96\NG960120.doc

cc: L. B. Swenzinski
L. Liu
B. Fisher
J. Franz
G. Kelly (NRC-NRR)
H. Miller (Region III)
NRC Resident Office
Docu