

Arizona Public Service Company

RECEIVED
NRC

1984 NOV 26 PM 1:38

REGION V USE

November 9, 1984
ANPP-31091-TDS/TRB

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Reactor Safety and Projects

Subject: Deficiency Evaluation Report DER 84-82
A 50.55(e) Evaluation Relating To Borg-Warner Check
Valves
File: 84-019-026; D.4.33.2


Reference: Telephone conversation between C. Sorenson and T. Bradish
on October 10, 1984

Dear Sir:

The NRC was notified of the subject Deficiency Evaluation in the
referenced telephone conversation with a determination of reportability
to be made within thirty (30) days (November 10, 1984).

The deficiency has subsequently been determined to be Not Reportable
under the requirements of 10CFR50.55(e), therefore no written report is
required. Necessary documentation of the evaluation will be maintained
in APS files.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Production
ANPP Project Director

EEVB/TRB/nj

cc: See Page Two

Mr. T. W. Bishop
DER 84-82
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
D. B. Karner
W. E. Ide
D. B. Fasnacht
A. C. Rogers
L. A. Souza
D. E. Fowler
T. D. Shriver
C. N. Russo
J. Vorees
J. R. Bynum
J. M. Allen
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
R. P. Zimmerman
L. Clyde
M. Woods
T. J. Bloom

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339