



Goodman-Smith diagram for high cycle fatigue (>10<sup>6</sup> cycles) at 100% load for Shoreham engines DG101 and DG102.

8412140015 841022  
PDR ADDOCK 05000322  
G PDR