



Mean and cyclic stresses for infinite fatigue life. The shaded region shows the combination of stress amplitude (σ_a) and mean stress (σ_m) that will not initiate cracks.

8412140406 840910
PDR ADDCK 05000322
G PDR