

**DUKE POWER COMPANY**

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

84 OCT 5 P 3: 06

TELEPHONE  
(704) 373-4531

October 1, 1984


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30303

Re: RII:PKV/PHS  
50-413/84-44  
50-414/84-21

Dear Mr. O'Reilly:

Our response to Part 1 of Violation No. 413/84-44-01, 414/84-21-01 stated that certain corrective actions on R-6a no. 670 would be complete by October 1, 1984. The review of equipment maintenance records has been completed on time. However, two Non-conformances (NCIs) were identified in this review and additional time is needed to resolve these items. These NCI's will be resolved by November 1, 1984.

Very truly yours,



Hal B. Tucker

RWO/mjf

cc: NRC Resident Inspector  
Catawba Nuclear Station

Mr. Robert Guild, Esq.  
Attorney-at-Law  
P. O. Box 12097  
Charleston, South Carolina 29412

Palmetto Alliance  
2135½ Devine Street  
Columbia, South Carolina 29205

Mr. Jesse L. Riley  
Carolina Environmental Study Group  
854 Henley Place  
Charlotte, North Carolina 28207

8410250075 841001  
PDR ADOCK 05000413  
Q PDR

1/0  
IEDI