



GPU Nuclear Corporation  
Post Office Box 480  
Route 441 South  
Middletown, Pennsylvania 17057-0191  
717 944-7621  
TELEX 84-2386  
Writer's Direct Dial Number:  
5211-85-2019

February 13, 1985

Office of Nuclear Reactor Regulation  
Attn: J. F. Stolz, Chief  
Operating Reactor Branch No. 4  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. Stolz:

Three Mile Island Nuclear Station Unit 1 (TMI-1)  
Operating License No. DPR-50  
Docket No. 50-289  
Inspection Report (I.R.) 84-37: Comment


NRC Inspection Report 84-37 dated January 3, 1985 states incorrectly (Section 4.0) that the controls for Emergency Feedwater Pump Recirculation Valves EF-V8 A, B and C are to be upgraded to safety grade during the first refueling outage after restart.

GPUN's letter of March 22, 1983 (5211-83-055) describes our commitment to lock open these valves, thereby eliminating the need for upgrading the valve controls to safety grade. In addition, EFW Pump Recirculation Line Piping from the EF-V8 valves to the condensate storage tanks has been upgraded to Seismic Class 1 as described in Section III.1 of our letter of October 3, 1984 (5211-84-2244). Since EF-V8 A, B and C are required to remain locked open during normal plant operation and under postulated accident conditions they are not included in the TMI-1 Environmental Qualification Master List.

We wish to clarify that GPUN has no plans to upgrade EF-V8 A, B and C to safety grade. Any future modifications to these valves which may prove to be desirable would be accomplished in accordance with 10 CFR 50.59.

Sincerely,

8502190266 850213  
PDR ADOCK 05000289  
Q PDR

  
H. D. Hukill  
Director, TMI-1

MRK/HDH/spb

cc: R. Conte  
D. Vito

*Aoo!*  
*1/0*