



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

February 12, 1985

Director
Office of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos. 50-282 License Nos. DPR-42
50-306 DPR-60

Unit 1 Inservice Inspection Summary Report

Attached for your review are four copies of the report, "Inservice Inspection - Examination Summary, Prairie Island Nuclear Generating Plant - Unit 1, October 23 to November 4, 1984, Steam Generator Tube - Eddy Current Examination, Inspection Period 3".

This report is a summary of steam generator tube eddy current examinations performed on steam generators No. 11 and No. 12 at Prairie Island - Unit 1. The examinations were performed during the period from October 23 through November 4, 1984 after tube leakage was detected via secondary side chemical analysis.

A summary of the tubes exhibiting eddy current indications and the total number of tubes plugged to date are exhibited in Appendices B and C of the report.

David Musolf
Manager - Nuclear Support Services

DMM/EFE/dab

- c: Regional Administrator-III, NRC (2 copies of attachment)
NRR Project Manager, NRC (1 copy of attachment)
Resident Inspector, NRC (w/o attachment)
G Charnoff (w/o attachment)
H Baron, Chief Boiler Ins., State of MN (1 copy of attachment)
S Tack, Hartford Ins. (1 copy of attachment)

Attachment

8502200366 850212
PDR ADOCK 05000282
Q PDR

A047
1/3