



NIAGARA MOHAWK POWER CORPORATION / 300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202 / TELEPHONE (315) 474-1511

September 27, 1984  
(NMP2L 0172)

Mr. R. W. Starostecki, Director  
U. S. Nuclear Regulatory Commission  
Region I  
Division of Project and Resident Programs  
631 Park Avenue  
King of Prussia, PA 19406

Re: Nine Mile Point - Unit 2  
Docket No. 50-410

Dear Mr. Starostecki:

Enclosed is an interim report, in accordance with 10CFR50.55(e), for the problem concerning Rosemount master trip units. This condition was reported via tel-con to S. Collins of your staff on August 28, 1984.

Very truly yours,

C. V. Mangan  
Vice President  
Nuclear Engineering and Licensing

CVM/GG/pbd

xc: Director of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

R. A. Gramm, NRC Resident Inspector

Project File (2)

8411070311 840927  
PDR ADDCK 05000410  
S PDR

1/1 IE 27

NIAGARA MOHAWK POWER CORPORATION  
NINE MILE POINT - UNIT 2  
DOCKET NO. 50-410

Interim Report for a Problem  
Concerning Rosemount Master Trip Units  
(55(e)-84-34)

Description of the Problem

During the field acceptance test on the Rosemount master trip units, it was noticed that some of the units exhibited a spurious and random operation of the setpoints. These units are used in Nuclear Steam Supply System safety-related systems.

Corrective Action

The corrective action is still being investigated by General Electric Company and a final report will be submitted by December 12, 1984.