

WOLF CREEK

NUCLEAR OPERATING CORPORATION

Neil S. "Buzz" Carns
Chairman, President and
Chief Executive Officer

April 19, 1996

WM 96-0054

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-137
Washington, D. C. 20555


Subject: Docket No. 50-482: Licensee Event Report 96-004-00

Gentlemen:

The attached Licensee Event Report is being submitted pursuant to 10 CFR 50.73 (a) (2) (i) (B) concerning a condition that resulted in the plant being in violation of Technical Specification 3.5.4. This was due to a cognitive personnel error in that an inadequate clearance order allowed power to remain available to discharge valves for a safety injection pump during testing.

If you should have any questions regarding this submittal, please contact me at (316) 364-4100, or Mr. William M. Lindsay at extension 8760.

Very truly yours,



Neil S. Carns

NSC/jad

Attachment

cc: L. J. Callan (NRC), w/a
W. D. Johnson (NRC), w/a
J. F. Ringwald (NRC), w/a
J. C. Stone (NRC), w/a

240000

9604240051 960419
PDR ADOCK 05000482
S PDR