

Duke Power Company  
McGuire Nuclear Generation Department  
12700 Hagers Ferry Road (MGU1VP)  
Huntersville, NC 28078-8985

T. C. McMEEKIN  
Vice President  
(704) 875-4800  
(704) 875-4809 Fax



**DUKE POWER**

DATE: April 18, 1996

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555


Subject: McGuire Nuclear Station Unit 1 and 2  
Docket No. 50-369

Licensee Event Report 370/96-01, Revision 1  
Problem Investigation Process No.: 2-M96-0332

Gentlemen :

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 370/96-01, Revision 1, concerning Unit 2 Refueling Water Storage Tank Level Instrumentation Inoperability during cold weather conditions. This revision is being submitted to include editorial changes to the report. This report is being submitted in accordance with 10 CFR 50.73 (a) (2) (i) and 10 CFR 50.73 (a) (2) (ii). The health and safety of the public was not affected as a result of this event.

Very truly yours,

  
T.C. McMeekin

JWP/bcb

020201

Attachment

cc: Mr. S.D. Ebner  
Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta St., NW, Suite 2900  
Atlanta, GA 30323

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, GA 30339

Mr. Victor Nerses  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Reactor Regulation  
Washington, D.C. 20555

Mr. George Maxwell  
NRC Resident Inspector  
McGuire Nuclear Station

9605030015 960418  
PDR ADOCK 05000370  
S PDR

IE22  
11

bxc: B.L. Walsh (EC11C)  
Zack Taylor (CNS)  
G.A. Copp (EC050)  
J.I. Glenn (MG02ME)  
P.R. Herran (MG01VP)  
Cindy Davis (MG01CP)  
J.E. Burchfield (ONS Reg Compliance)  
G.H. Savage (EC06E)  
G.B. Swindlehurst (EC11-0842)  
R.F. Cole (EC05N)  
J.M. Arye (EC05N)  
Tim Becker (PB02L)  
P.M. Abraham (EC08I)  
R.B. White (MG01VP)  
L.V. Wilkie (ON03SR)  
D.P. Kimball (CN05SR)  
NSRE Support Staff (EC05N)  
Kay Crane (MG01RC)  
Rich Casler (EC05N)  
C.M. Misenheimer (EC08I)