


TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER • 400 NORTH OLIVE STREET, L.B. 81 • DALLAS, TEXAS 75201

BILLY R. CLEMENTS
VICE PRESIDENT, NUCLEAR OPERATIONS

March 5, 1985
TXX-4432



Mr. D.R. Hunter, Chief
Reactor Project Branch 2
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

Docket No.: 50-445

COMANCHE PEAK STEAM ELECTRIC STATION
BUTT SPLICES
QA FILE: CP-85-07, SDAR-168
FILE NO.: 10110

Dear Mr. Hunter:

On February 8, 1985 we verbally notified your Mr. D. Hunnicutt of a deficiency regarding the reinspection of electrical cable butt splices identified by the Technical Review Team (TRT) as Items I.a.2 and I.a.3.

We are continuing our evaluation and anticipate completion by April 3, 1985.

Very truly yours,

A handwritten signature in cursive script, appearing to read "Billy R. Clements".

BRC:tlg

cc: NRC Region IV - (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8503120499 850305
PDR ADOCK 05000445
S PDR

1/0
IE-27

8501