

Enclosure 3

Revised Page E2-4
for

Plant Hatch Unit 2

Monthly Operating Report
March 1996

9605140134 960510
PDR ADOCK 05000321
R PDR

UNIT SHUTDOWNS AND POWER REDUCTIONS

UNIT NAME: E. I. HATCH -- UNIT TWO

REPORT MONTH: MARCH 1996

DOCKET NO: 50-366

DATE: APRIL 3, 1996

COMPLETED BY: S. B. ROGERS

TELEPHONE: (912) 367-7781 x2878

NO.	DATE	T Y P E	DURATION (HOURS)	R E A S O N	M E T H O D	LICENSEE EVENT REPORT NUMBER	S Y S T O P M E	COMPONENT CODE (SUBCODE)	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
96-003	960312	S	82.7	A	2	N/A	CC	VALVEX (X) (B)	The unit was manually scrammed to replace Main Steam Line SRVs "D" and "H". Main Steam Line SRVs "D" and "H" were replaced, and the unit was returned to rated thermal power.

TYPE:

F-FORCED
S-SCHEDULED

REASON:

A-EQUIPMENT FAILURE (EXPLAIN)
 B-MAINTENANCE OR TEST
 C-REFUELING
 D-REGULATORY RESTRICTION
 E-OPERATOR TRAINING & LICENSE
 F-ADMINISTRATIVE
 G-OPERATIONAL ERROR (EXPLAIN)
 H-OTHER (EXPLAIN)

METHOD:

1-MANUAL
 2-MANUAL SCRAM
 3-AUTOMATIC SCRAM
 4-CONTINUATIONS
 5-LOAD REDUCTION
 9-OTHER (EXPLAIN)

EVENTS REPORTED INVOLVE
 A GREATER THAN 20%
 REDUCTION IN AVERAGE
 DAILY POWER LEVEL FOR
 THE PRECEDING 24 HOURS.