



DUKE POWER

September 5, 1996


U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Errata Letter for Licensee Event Report (LER) 414/96-003

Gentlemen:

The above noted LER was submitted to you by letter, dated September 3, 1996. It has come to our attention that the cover sheet to this LER inadvertently denoted the incorrect docket number. Nuclear Regulatory Commission Report Form 366 correctly denoted this LER as docket and LER number LER 414/96-003, Technical Specification 3.0.3 Required Shutdown Due to Ventilation System Motor Failures.

Very truly yours,


W. R. McCollum, Jr.

Attachment

cc: Mr. S.D. Ebner
Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

INPO Records Center
700 Galleria Place
Atlanta, GA 30339-5957

Mr. P.S. Tam
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. John Hoffman
Marsh & McLennan Inc. (Nuclear)
301 Tresser Blvd.
Stamford, CT 06904

Mr. R. J. Freudenberger
NRC Resident Inspector
Catawba Nuclear Station

9609120327 960905
PDR ADOCK 05000414
S PDR

120016

IE22%