



**Commonwealth Edison**  
Byron Nuclear Station  
4450 North German Church Road  
Byron, Illinois 61010

April 22, 1985

LTR: BYRON 85-0588

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 10555

Dear Sir:

The enclosed Licensee Event Report from Byron Generating Station is being re-transmitted to you due to duplication of a previous Licensee Event Report number.

This report is number 84-043-00 Docket No. 50454. Report number 84-042-00 Docket No. 50-454, titled "Failure to Perform ASME Section XI Testing" is to be removed. No changes in the text or abstract have been made.

Very truly yours,

R. E. Querio  
Station Superintendent  
Byron Nuclear Power Station

REQ/gt

Enclosure: Licensee Event Report No. 84-043-00

cc: J.G. Keppler, NRC Region III Administrator  
J. Hinds, NRC Resident Inspector  
INPO Record Center  
CECo Distribution List

#8/018

8505170572 850422  
PDR ADDCK 05000454  
S PDR

IE22  
1/1