

Farley Exit Meeting Input - RC Wilson 11/20/87 8:35 am

'92 JUN -2 P12:11

① Raychem/Chico seals (package 29G) - NUREG 0588 Cat. II
Qualification not demonstrated because bonding of the Raychem material to the metal pipe nipple under LOCA conditions (including chemical spray) was not been addressed.

② Target Rock SOV cable entrance seal (package 35)
~~Qualified for the seal~~
Qualification not demonstrated - ~~wasn't~~ there is no documentation. The seal design differs significantly from any for which qualification has been demonstrated - concerns include (a) the loading concern with the Chico seal and (b) the presence of ~~an~~ an internal void. Further, the SOV package claims qualification to 10 CFR 50.49 - the Chico seal package is not acceptable (apart from the bonding concern) at that level and would be at best a weak contributor to a 50.49 qualification argument. If the licensee drops the SOV qualification level to NUREG 0588 Cat. II he must justify doing so. As long as the SOV is 50.49, the seal must also be at that level.