

Georgia Power Company
40 Inverness Center Parkway
Post Office Box 1295
Birmingham, Alabama 35201
Telephone: 205 877-7279

J. T. Beckham, Jr.
Vice President—Nuclear
Hatch Project



HL-2388
003909

August 26, 1992

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

PLANT HATCH - UNITS 1, 2
NRC DOCKETS 50-321, 50-366
OPERATING LICENSES DPR-57, NPF-5
TAC NOS. M82056, M80424

Gentlemen:

Enclosed is a revised page to Table 4-2 of the IGSCC Flaw Evaluation and Weld Overlay Activity Report previously submitted on March 3, 1992. The page was revised based on discussions with the NRC staff.

Sincerely,

J. T. Beckham, Jr.

JKB/cr

Enclosure

cc: Georgia Power Company
Mr. H. L. Sumner, General Manager - Nuclear Plant
NORMS

U.S. Nuclear Regulatory Commission, Washington, D.C.
Mr. K. Jabbour, Licensing Project Manager - Hatch

U.S. Nuclear Regulatory Commission, Region II
Mr. S. D. Ebnetter, Regional Administrator
Mr. L. D. Wert, Senior Resident Inspector - Hatch

9209020004 920826
PDR ADU.K 05000321
PDR

A001
4/1

Table 4-2 (concluded)

Shrinkage Stresses at Unrepaired Welds in Hatch Unit 1
Recirculation System Following 1991 Overlays

Weld	Shrinkage Stress (ksi)
12BR-B-2	2.19
12BR-B-4	1.59
12BR-B-5	1.57
12BR-C-1	12.93
12BR-D-1	6.02
12BR-D-4	5.51
12BR-D-5	6.33
12BR-E-1	9.42