



ENTERGY

Entergy Operations, Inc.  
P.O. Box 8  
Kilona, LA 70086  
Tel 504 739 6774

R. F. Burski  
Director  
Nuclear Safety  
Waterford 3

W3F1-92-0410  
A4.05  
QA

September 17, 1992

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

Subject: Waterford 3 SES  
Docket No. 50-382  
License No. NPF-38  
Ten Year Inservice Inspection Program, with Relief Requests  
Revision 5

Gentlemen:

Entergy Operations, Inc. hereby submits by attachment, Revision 5 of the Waterford 3 Ten Year Inservice Inspection Program for your records. The new revision includes enhancements as a result of field use of the program and provides information which was gained during our past refueling outages. Section 6 of this revision includes new and revised relief requests for your review. Specifically, Relief Requests ISI-001, ISI-006, and ISI-012 have been revised, and ISI-013 is a new relief request.

Should you have any questions, please contact Ms. B.R. Loetzerich at (504) 739-6636.

Very truly yours,

RFB/BRL/ssf  
Attachment

(w/Attachment)  
cc: J.L. Milhoan, NRC Region IV  
NRC Resident Inspectors Office

(w/o Attachment)  
cc: D.L. Wigginton, NRC-NRR  
R.B. McGehee  
N.S. Reynolds

9209250062 920917  
PDR ADDCK 05000382  
Q PDR

A047  
11