

- 15 1. NOTE: SEELINGER TO BRUNNER
5/16/78
- 16 2. MEMO: ZEWE TO SEELINGER
5/15/78
- 17 3. PROBLEM REPORT JOHN BRUN...
TO R.J. TOOLE 11/3/77
- 18 4. OCT 19, 1977 LOSS OF FEED WATER
TRIP REPORT
5. FQ 1577
- P.E. 6. ECM S-4562

Frank
Gangenberg
101-262-5350

7911090 539

~~7911090 535~~

MEMO from:

J. L. SEELINGER

CC Begilla - task
Zewe - info

5/16/78

John Brummer

Subj: Water in IA

1. See Zewe's attached correspondence
2. There are some good ideas here.
3. The quickest route to go on SAV 376 might be a CPU problem report.
4. With respect to COV 12, it will undoubtedly be a capital project so let's get paper moving.
5. Dew cell - same as #4
Target date on PR 5/18
Others: initial paper by 6/16

Jm