

DCD/DCB

NOV 25 1992

Cardiovascular Consultants
ATTN: Denise A. Piotrowski, R.N., B.S.N.
Practice Manager
610 N. Michigan Street, Suite 400
South Bend, IN 46601

License No. 13-26295-01
Docket No. 030-32112

Dear Ms. Piotrowski:

SUBJECT: NRC SPECIAL INSPECTION REPORT NO. 92-001

This refers to the special inspection conducted by W. P. Reichhold and R. Anderson of this office on April 8, 1992. That inspection resulted from information developed during an investigation conducted by the NRC Office of Investigations. This special inspection was performed to determine if your facility was the same as described in your license application. The inspection findings were discussed with you by telephone on May 18, 1992.

During the inspection, it was noted that you had no Radiation Safety Officer and no individual authorized to use byproduct (radioactive) material. Because your license was terminated on July 17, 1992, we have no further questions regarding these matters.

Sincerely,

John A. Grobe, Chief
Nuclear Materials Safety Branch

yes
RIII
Reichhold/sd

11/24/92

RIII

Holt

11/24/92

RIII

Grobe

11/25

9212110142 921125
PDR ADDCK 03032112
C PDR

IE07