

NOV 25 1992

Docket No. 50-186

University of Missouri-Columbia  
ATTN: Dr. James J. Rhyne  
Director, Research Reactor Facility  
Research Park  
Columbia, MO 65201

Dear Dr. Rhyne:

SUBJECT: ROUTINE SAFETY INSPECTION AT THE UNIVERSITY OF MISSOURI-COLUMBIA  
RESEARCH REACTOR

This refers to the routine safety inspection conducted by Mr. C. Cox of this office on November 2-5, 1992. The inspection included a review of authorized activities for the University of Missouri (Columbia) Research Reactor facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, interviews with personnel, and observation of activities in progress.

No violations of NRC requirements were identified during the course of this inspections.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by J. W. McCormick-Barger"

J. W. McCormick-Barger, Chief  
Emergency Preparedness and  
Non-Power Reactor Section

Enclosure: Inspection Report  
No. 50-186/92004(DRSS)

SEE ATTACHED DISTRIBUTION

RIII

RIII

Cox/jp

McCormick-Barger

150614

11/25/92

9212160090 921125  
PDR ADOCK 05000186  
Q PDR

IE35  
1/1

University of Missouri-Columbia

2

NOV 25 1992

Distribution:

cc w/enclosure:

DCD/DCB (RIDS)

OC/LFDCB

Al Adams, NRR

Dr. William Vernetson, Director  
of Nuclear Facilities