



23-24
Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

November 3, 1983

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-306 License No. DPR-60

One Steam Flow Transmitter Failed Low

The License Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2.(a), since a reactor protection system or engineering safety feature instrument setting was found to be less conservative than those established by the Technical Specifications but which does not prevent the fulfillment of the functional requirements of the affected system.

David Musolf for

David Musolf
Manager - Nuclear Support Services

DMM/TAP/dab

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman

Attachment

1E22
1/1
83 RETROFIT

NOV 14 1983