

No. 2-81-16/3L

Dear Mr. Grier:

This L.E.R. concerns inoperability of the RCIC system due to failure of the turbine trip-throttle valve to reset using the limitorque operator. Governing Technical Specification is 3.5.0.2.

U. S. NUCLEAR REGULATORY COMMISSION

LICENSING EVENT REPORT

[illegible]

810 33 10642

5