

MATERIALS LICENSE  
SUPPLEMENTARY SHEET

License number

13-02841-03

Docket or Reference number

Amendment No. 02

The Dalton Foundaries, Inc.  
P. O. Box 1388  
Warsaw, IN 46580

In accordance with application dated June 24, 1983, License Number 13-02841-03 is amended as follows:

Item 2 (Address) is changed from Lincoln and Jefferson Streets, Warsaw, Indiana 46580 to P. O. Box 1388, Warsaw, Indiana 46580.

Items 6., 7., 8., and 9. are amended to add:

- |   |   |  |
|---|---|--|
| 6. Byproduct, source, and/or special nuclear material | 7. Chemical and/or physical form                    | 8. Maximum amount that licensee may possess at any one time under this license |
| B. Cesium-137   | B. Sealed source (3M Model No. 4D6L, 4F65, or 4F6P) | B. One source not to exceed 5000 millicuries                                   |

9. Authorized Use

- B. To be used in Ronan Engineering Model No. X90-SA-1 source holder for level measurement.

Conditions 10., 12., and 17. are amended to read:

10. Licensed material shall be used only at the licensee's facilities at Lincoln and Jefferson Streets, Warsaw, Indiana.
12. Licensed material shall be used by, or under the supervision of, Gerald Kenny, Daryl Woodward, Richard Gallentine, Boyd Wear, James Priser, or Tom Flees.
17. Except as specifically provided otherwise by this license, the licensee shall possess and use licensed material described in Items 6, 7, and 8 of this license in accordance with statements, representations, and procedures contained in applications dated February 11, 1980 and June 24, 1983. The Nuclear Regulatory Commission's regulations shall govern the licensee's statements in applications or letters, unless the statements are more restrictive than the regulations.

8506100454 850510  
REG3 LIC30  
13-02841-04 PDR

Control No. 75571

MATERIALS LICENSE  
SUPPLEMENTARY SHEET

License number

13-02841-03

Docket or Reference number

Amendment No. 02

Conditions 18., 19., and 20. are added:

18. The Radiation Protection Officer for the activities authorized by this license is Richard A. Gallentine.
19. The licensee shall operate each gauge within the manufacturer's specified temperature limits such that the shielding and shutter mechanism of the source holder is not compromised.
20. The licensee shall establish "lock-out" procedures to assure that prior to maintenance or repair in or around equipment to which licensed gauges are mounted, steps are taken to terminate the radiation beams, (e.g., "lock-out" shutters, placement of "beam stoppers," etc.) to prevent individuals from entering the radiation beam.

For the U.S. Nuclear Regulatory Commission

Original Signed by Bruce s. Mallett

Date AUG 3 1983

By Bruce S. Mallett

Materials Licensing Section, Region III

Control No. 75571

# CONVERSATION RECORD

TIME

200p

DATE

5/7/84

TYPE

☐ VISIT

☐ CONFERENCE

☒ TELEPHONE

☒ INCOMING

☐ OUTGOING

ROUTING

NAME/SYMBOL INT

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU

Marleen Kayler

ORGANIZATION (Office, dept., bureau, etc.)

ROMAN Engineering

TELEPHONE NO:

SUBJECT

License No. 13-02841-03

SUMMARY

1) How many sources can Dalton foundry get under their license.

Items 6.B., 7.B., 8.B., 9.B says one source  
3M 4F65 in NONAN X90-SA-1

Item 6.C., 7.C., 8.C., 9.C says one source  
3M 4F65 etc in NONAN X90-SA-1.

B and C appear to be same

Licensee amendment request for amend 03  
dated 9/7/83 requests an additional source

Based on above, I told ROMAN that Dalton could actually have 2 sources, one under amendment 02 Item 6,7,8,9 B and another under amend 03 Items 6,7,8,9 C. This appears to have been the licensee's intent.

ACTION REQUIRED

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

DATE

Dixie Matson

ACTION TAKEN

SIGNATURE

TITLE

DATE

## CONVERSATION RECORD

TIME

DATE

8/3/83

TYPE

☐ VISIT☒ CONFERENCE☐ TELEPHONE☐ INCOMING☐ OUTGOING

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT  
WITH YOU

Don Brown.

ORGANIZATION (Office, dept., bureau,  
etc.)

Dillon Foundries

TELEPHONE NO.

ROUTING

NAME/SYMBOL

INT

SUBJECT

Amendment to spec. No. 13-02841-03.

Control # 15186.

SUMMARY

B. Mallett explained that in order to authorize - need  
the following:

1. Lock-out procedures.
2. Precautions against exceeding temp. of gauge.

B. Mallett and Don Brown agreed that license  
could be conditioned for such.

ACTION REQUIRED

Same with conditions.

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

Bruce Mallett

DATE

8/3/83

ACTION TAKEN

SIGNATURE

TITLE

DATE