



CORY LABORATORIES, INC.

823 5TH STREET • MENOMINEE, MICHIGAN 49858 • (906) 863-9336

Reg III DCS 04/20/81

February 24, 1981

Mr. John W. Cooper
U. S. Nuclear Regulatory Commission
Division of Fuel Cycle & Material Safety
Washington, D. C. 20555

Applicant	7118
License No.	840(34)
License Fee	Amendment
Type of Fee	4/14/81
Date Check Recd	
Received By	Brown

U.S. NUCLEAR REG
COMMISSION
MAIL SECTION

MAR 2 AM 11 53

RECEIVED

Dear Mr. Cooper:

Cory Labs has recently purchased a used Sigma I gas chromatograph which contains a Ni-63 detector. As the first step toward licensing this source I've sent you what information I have and am asking a few questions.

- 1) I've attached a copy of Cory's present license. As I understand it our license merely has to be amended to include the extra source, requiring a \$40.00 fee.
- 2) This source was formerly (or is) covered by license #35 42-60 which (I think) belongs to Rocky Mountain Geo-Tech, 840 Greg St., Reno, Nevada, 89431.
- 3) I understand that I will need no special training to maintain the source or to obtain the license.
- 4) I've also attached 3 pages from the equipment manual describing the leak test procedure. I've been in touch with NSSI and I feel I've got that part under control.

I can't think of any other information you may need but I may have easily missed something. I trust you'll let me know if I have.

Thanks for your time.

RECEIVED BY LFMB	
Date	3/4/81
Log	Brown
By	Brown
Orig. To	
Action Com. l.	4/16/81

Sincerely,

CORY LABORATORIES, INC.

J. A. Forst

SAF

8104300444

JAF:rmf

Enclosure

Laboratories Dedicated to Environmental Control