



Omaha Public Power District

1623 HARNEY # OMAHA, NEBRASKA 68102 # TELEPHONE 536-4000 AREA CODE 402

May 15, 1981

Director of Nuclear Reactor Regulation
ATTN: Mr. Robert A. Clark, Chief
Operating Reactors Branch No. 3
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555



Reference: Docket No. 50-285

Gentlemen:

Attached is one copy each of two sets of revision pages for incorporation into the Commission's copy of the Fort Calhoun Station Unit No. 1, Ten Year In-service Inspection (ISI) Plan.

The changes on pages 146, 187, 191, and 193 are the result of ISI examination credit taken on inspections performed to satisfy the requirements of IE Bulletin 79-17. This eliminates duplication of efforts and maintains the appropriate number of weld examinations to be conducted each ten years. The changes on pages 168, 179, 188, 189, Figures B-33, B-37, B-39, B-40, C-56, C-58, and C-61 account for errors in the location and/or number of welds on a given piping system as determined by field survey. Changes on pages B-32 and B-42 correct errors in listed calibration blocks for use in the examinations of these piping systems. The changes on page 173, Figures A-1, B-22a, and B-43 incorporate information obtained during the 1980 refueling outage.

Sincerely,

W. C. Jones
Division Manager
Production Operations

WCJ/KJM/TLP:jmm

Attachment

cc: LeBoeuf, Lamb, Leiby & MacRae
1333 New Hampshire Avenue, N.W.
Washington, D.C. 20036

A047
s
1/1

8105270088
I