

DEC 29 1992

DCD/DCB

Snell Environmental Group, Inc.
ATTN: Pratap Rajadhyaksha
President
1120 May Street
Lansing, MI 48906

License No. 21-18962-01
Docket No. 030-17407

Dear Mr. Rajadhyaksha:

This refers to the routine safety inspection conducted by Mr. Michael F. Weber of this office on December 17, 1992, of activities authorized by NRC Byproduct Material License No. 21-18962-01, and to the discussion of our findings with Mr. David Fildey of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appear to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The response directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Gary L. Shear, Chief
Nuclear Materials Inspection
Section 2

Enclosure: Notice
of Violation

cc w/ enclosure:
DCD/DCB (RIDS)

070003

RIII
Weber

12/29/92

RIII
Shear

12/29/92

9301080060 921229
PDR ADDCK 03017407
C PDR

IE07