

LER



ATOMIC POWER COMPANY •

Box 450, RFD 2  
Wiscasset, Maine 04578

June 3, 1981



United States Nuclear Regulatory Commission  
Directorate of Regulatory Operations  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Reference: License No. DPR-36 (Docket No. 50-309)

Dear Sir:

Pursuant to the requirements of Technical Specification 5.9.1.6.b, the Maine Yankee Atomic Power Company hereby submits the following report.

During routine shutdown refueling operations, at the completion of fuel handling activities and with greater than 23 feet of water in reactor cavity service water cooling to secondary component coolers was interrupted for a period of approximately 30 minutes. This is contrary to the requirements of Technical Specification 3.13.A.4. During the entire period there was no significant increase in RHR or SCC temperature.

Sincerely,

MAINE YANKEE ATOMIC POWER COMPANY

*Edwin C. Wood*

Edwin C. Wood  
Plant Manager

ECW/ps

M007  
5  
1/0

POOR ORIGINAL

5 8106090 357