

INSPECTION REPORT NUMBER 9th-001

APPENDIX C - SUPPLEMENTARY INFORMATION

Licensee: DFCI

License No.: 20-19261-02

- ☐ Uncorrected/repeated noncompliance
- ☐ Unusual occurrence, conditions, etc.
- ☐ Basis for change of Category or Priority

- ☐ Unresolved items
- ☒ Inspector's comments

NW 13 (annotated in text)

- weekly survey action level @ 37,313 dpm/100 Lm²
- Hot lab not reviewed on survey list
- No hood flow date check in May 684
- No record of flow check in May 784
- 6 waste barrels stored in May 784, from assorted research labs, no designated supervisor of area (waste control location process)