

DMB

MAY 20 1985

Docket No. 50-341

The Detroit Edison Company
ATTN: Wayne H. Jens
Vice President
Nuclear Operations
6400 North Dixie Highway
Newport, MI 48166

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. P. M. Byron, M. E. Parker, and D. C. Jones of this office on April 7-30, 1985, of activities at Fermi 2 authorized by Facility Operating License No. NPF-33 and to the discussion of our findings with R. S. Lenart at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During the inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

8505280202 850520
PDR ADOCK 05000341
Q PDR

IE01
1/1

Detroit Edison Company

2

MAY 20 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signe by R. C. Knop"

R. F. Warnick, Chief
Projects Branch 1

Enclosures:

1. Appendix, Notice
of Violation
2. Inspection Report
No. 50-341/85021(DRP)

cc w/enclosures:

L. P. Bregni, Licensing
Engineer
P. A. Marquardt, Corporate
Legal Department
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
Harry H. Voigt, Esq.
Nuclear Facilities and
Environmental Monitoring
Section

RIII

Stasek/kr
05/17/85

RIII

Chris
Chrisotimos

RIII

ack
Warnick
5/20/85