

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

35 MAY 14 All : May 9, 1985

BLRD-50-438/82-20  
BLRD-50-439/82-18

U.S. Nuclear Regulatory Commission  
Region II  
Attn: Dr. J. Nelson Grace, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Dear Dr. Grace:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - OMISSIONS TO AUXILIARY FEEDWATER  
PUMP DRAWINGS - BLRD-50-438/82-20, BLRD-50-439/82-18 - EIGHTH INTERIM  
REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
R. V. Crlenjak on February 25, 1983 in accordance with 10 CFR 50.55(e) as  
NRC BLN BLP 8207. This was followed by our interim reports dated March 25,  
July 20, September 7, and December 14, 1982, and April 6 and December 5,  
1983 and November 28, 1984. Below is our eighth interim report. We expect  
to submit our next report on or about December 18, 1985.

The auxiliary feedwater pump vent, drains, and turbine cooling water  
interconnecting piping analysis has been completed for units 1 and 2.  
Support design work for both units is in progress. Further information  
will be provided in our next report.

If you have any questions, please get in touch with R. H. Shell at FTS  
858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Domes*  
for J. W. Hufham, Manager  
Licensing and Regulations

cc: Mr. James Taylor, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8505280270 850509  
PDR ADDCK 05000430  
S PDR

Official Copy  
IE 27 1/0