

APPENDIX A
NOTICE OF VIOLATION

Universal Technical Testing Laboratories, Inc.
Collingdale, Pennsylvania 19023

Docket No. 030-05993
License No. 37-00453-03

As a result of the inspection conducted on May 2, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violations were identified:

- A. Condition 17 of License No. 37-00453-03 requires that licensed material be possessed and used in accordance with statements, representatives and procedures contained in application dated July 20, 1979 and letter dated October 6, 1980.

Item 6 (g) of the revised section of "Internal Inspection Systems Or Other Management Controls", which was included with your application dated July 20, 1979, requires that a radiation safety audit of each radiographer and assistant be performed at intervals of not more than three months.

Contrary to the above, as of May 2, 1985, you have failed to perform any radiation safety audits of radiographers since August, 1984.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Universal Technical Testing Laboratories, Inc. is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8507030648 850619
REG1 LIC30
37-00453-03 PDR

OFFICIAL RECORD COPY

DL UNIVERSAL TEST 85-01 - 0004.0.0
06/05/85