

PDR

APR 4 1974

H. D. Thornburg, Chief, Field Support and Enforcement Branch

FO # 342 - CAO #314

The enclosure to the subject document recommended issuance of a Bulletin relative to failure of components in the main steam isolation valve control system at Monticello. The affected components were installed as part of a modification made in early 1973. The licensee, in reporting the failure, stated its belief that such failure might be generic. We concur.

General Electric Company has reported the Monticello modification to Licensing in the form of Supplement 1 to APED-5750, with the statement that it is recommending this modification to all its customers, and will routinely supply the modified design on all future facilities. Licensing is currently evaluating the acceptability of this modification with a target date for decision of May 1, 1974. The Monticello occurrence is being considered in this evaluation.

To our knowledge, the only other facility which has made the Monticello modification is Cooper (we do not have information on Millstone 1 and Vermont Yankee 1).

Under the circumstances, we do not believe that a Bulletin is warranted. We will keep you and the Regions informed of the results of Licensing's evaluation.

151  
B. H. Grier, Assistant Director  
for Construction & Operation  
Directorate of Regulatory Operations

cc: G. Fiorelli, RO:III  
D. L. Ziemann, L  
R. W. Reid, L

50-263

OFFICE	<i>[Signature]</i>	<i>[Signature]</i> RO	<i>[Signature]</i> RO			
SURNAME	JHenderson:bs	KVSeyfrit	BHGrier			
DATE	4/3/74	4/3/74	4/3/74			

TO: ☒ B. H. Grier, RO

FS&EB ACTION CONTROL FORM

A. Action Code FO#342 / CRD: 314  
Name of Licensee and Facility BWR Facilities  
Docket No. or License No. \_\_\_\_\_  
Title Failure of MSIV Pilot Valves  
Origin Letter, Mayer to O'Leary 2/25/74 Date Rec'd \_\_\_\_\_

B. FS&EB Branch Coordinator:

Bryan X Dreher \_\_\_\_\_ H. D. Thornburg \_\_\_\_\_  
Ellis \_\_\_\_\_ Paulus \_\_\_\_\_

C. Action Requested of:

ADREMT \_\_\_\_\_ M&PFOB \_\_\_\_\_ EPB \_\_\_\_\_ RPB \_\_\_\_\_ ADCO X  
OB \_\_\_\_\_ TAB \_\_\_\_\_ OOE \_\_\_\_\_ REGION \_\_\_\_\_

Date Requested 3/19/74 Completion Requested by 3/27/74  
Reference Memorandum, Fiorelli to Thornburg dated 3/13/74.

D. Action Requested: Please evaluate the licensee's findings in the abnormal occurrence report as to whether or not they are generic and whether or not issuance of a bulletin is warranted.

E. Date Action Completed \_\_\_\_\_

Close-out (Date & Method) \_\_\_\_\_

Comments: If completion date is not consistent with your work schedule, please let us know.

cc: J. G. Davis

*Harold D. Thornburg*  
Harold D. Thornburg, Chief  
Field Support & Enforcement Branch  
Directorate of Regulatory Operations