



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
ARIZONA STATE OFFICE
3707 N. 7th Street
Phoenix, Arizona 85014

IN REPLY REFER TO:
1112 (951)
0058Q

Nuclear Regulatory Commission
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596

Attention: David D. Skov
Radiation Specialist
Nuclear Materials Safety Section

Gentlemen:

Pursuant to your requirements we have enclosed the four signed carbon copies of your Safety Inspection Report (NRC Form 591), License No. 02-17208-01.

We are taking the following steps to correct the problems identified:

Item 3C, We have a system to do inventories each six months and will complete an inventory of all three gauges by June 30, 1985.

Item 3d. We have completed the leak test of the gauge S/N M19113009. We are having the test evaluated and will file the results when we receive them. This gauge has been returned to storage in that office.

Item 3H. We are filing for an amendment to our license to make these corrections before June 30, 1985.

Sincerely,

Dean Bibles
State Director

Enclosure

8505290267 850523
REG5 LIC30
02-17208-01 PDR