

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

July 1, 1975

H. D. Thornburg, Chief, Field Support and Enforcement Branch
Office of Inspection and Enforcement, Headquarters

NORTHERN STATES POWER COMPANY (MONTICELLO)
DOCKET NO. 50-263
PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE
CRACKED FUEL PINS IN SPENT FUEL ASSEMBLIES

The attached communication covering the preliminary information regarding the cracked fuel pins in spent fuel assemblies at Monticello is forwarded with the recommendation it be issued as a "Preliminary Notification."

G. Fiorelli
G. Fiorelli, Chief
Reactor Operations

Attachment:
As stated

cc w/attachment:
J. G. Davis, DDFO
B. H. Grier, ADCO
R. F. Warnick, Regional Coordinator
J. G. Keppler, IE:III
IE Files
Central Files



9212070454 750701
PDR ADOCK 05000263
S PDR