

1 WRBagb

1 the TSI depth gauge measurements?

2 A Not directly, I was in and out of the room.

3 Q So you would not know, I assume then, what the
4 depth of the deepest crack was in the old 103 and what the
5 deepest crack was in 101, is that right, by measurement?

6 A No, that isn't right. I asked you if you could
7 give me the reference which you are addressing. There has
8 been a lot of material supplied, a lot of amended material
9 also and I just wondered if you would be kind enough to give
10 me a reference.

11 Q Have you -- I understood from your prefiled
12 testimony that you had occasion to review inspections
13 provided by LILCO to ascertain crack depths.

14 A The inspection provided by LILCO, I presume you
15 mean at Shoreham, allowed me to look at the new 103. There
16 was no instrumentation to allow me to independently
17 determine crack depth.

18 Q No, Dr. Anderson, I was not only referring to
19 that, I was referring to other LILCO dye penetrant, magnetic
20 particle, et cetera, inspection reports that in fact you
21 reference in your answer in your supplemental testimony I
22 think on the top of page 10.

23 MR. BRIGATI: Objection, Judge. That testimony
24 goes only to the replacement block. The questions being
25 asked by Mr. Farley related to the original 103 block and