



TFC Nuclear Associates, Inc.

WM DOCKET CONTROL
CENTER

'85 JUN 26 P4:04

425 Bridgeboro Road
Moorestown, N.J. 08057
(609) 778-4529

June 19, 1985

Dr. Michael Tokar
United States Nuclear Regulatory Commission
Engineering Branch - Division of Waste Management
Washington D.C.

Subject: TFC-TR-84(P) Topical Report
"Road Map" outline


Dear Dr. Tokar:

We sincerely apologize for the long delay in responding to your request to provide a "road map" which correlates on an item-by-item basis where in our topical report the new NRC acceptance criterias are addressed. Enclosed I have provided the outline that provides this information. In addition, the following items are also enclosed for your review:

1. Report to South Carolina Department of Health and Environmental Controls on venting of the NUHIC High Integrity Containers.
2. TFC Quality Assurance manual revision #1 recently revised to comply with 10 CFR 50 Appendix "B".
3. TFC Dewatering procedures for bead resins and powder resins.
4. TFC Dewatering Test results.

We hope that the above information will assist you in continuing our topical report review. Should you have any further questions or require any additional information please contact me.

Very truly yours,


John J. Chando, Jr.
President

JJC/cd

WM Record File

WM Project 76

Docket No. _____

PDR ☒ (Initial only)
LPDR _____

Distribution:

TOKAR
T. JOHNSON
(Return to W-1, 623-SS)

23

Enclosures - *Proprietary*

8507080223 850619
PDR WASTE
WM-76 PDR