

**Florida
Power**
CORPORATION

July 2, 1985
3F0785-07

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
Attn: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555


Subject: Crystal River Unit 3
Docket No. 50-302
Operating License No. DPR-72
ASME Section XI, Relief Request

Reference: Letter dated 6/19/85 from G. R. Westafer, FPC, to
H. R. Denton, NRC

Dear Sir:

The purpose of this letter is to correct the hydrostatic test pressure specified in the referenced letter. It has been determined that the system was hydrostatically tested to 110% of the design pressure, instead of 100% as previously communicated.

Sincerely,



G. R. Westafer
Manager, Nuclear Operations
Licensing and Fuel Management

DDG/feb

cc: Dr. J. Nelson Grace
Regional Administrator, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, N.W. Suite 2900
Atlanta, GA 30323

8507090132 850702
PDR ADOCK 05000302
P PDR

A047
1/0