

UNITED STATES ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

*Remanent (4)*  
*7/14/66*

<p>1. LICENSEE <b>The Carborundum Company The Carborundum Metals Company Division P. O. Box 32 Arkon, New York</b></p>	<p>2. REGIONAL OFFICE <b>U. S. Atomic Energy Commission Region II, Division of Compliance 50 Seventh Street, N. E. Atlanta, Georgia 30323</b></p>
<p>3. LICENSE NUMBER(S) <b>STB-440 (Docket No. 40-5001)</b></p>	<p>4. DATE OF INSPECTION <i>July 14, 1966</i></p>
<p>5. INSPECTION FINDINGS</p> <p><input checked="" type="checkbox"/> A. No item of noncompliance was found.</p> <p><input type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42</p> <p><input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42</p> <p><input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)</p> <p><input type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)</p> <p><input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)</p> <p><input type="checkbox"/> G. Storage containers were not properly labeled to show the quantity, date of measurement, or kind of radioactive material in the containers. 10 CFR 20.203(f) (4)</p> <p><input type="checkbox"/> H. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)</p> <p><input type="checkbox"/> I. Form AEC-3 was not properly posted. 10 CFR 20.206(c)</p> <p><input type="checkbox"/> J. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)</p> <p><input type="checkbox"/> K. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)</p> <p><input type="checkbox"/> L. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51</p> <p><input type="checkbox"/> M. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)</p> <p><input type="checkbox"/> N. Records of inventories were not maintained. 10 CFR 34.26</p> <p><input type="checkbox"/> O. Utilization logs were not maintained. 10 CFR 34.27</p> <p style="text-align: right; margin-right: 100px;"><i>William B. Ellis</i> (AEC Compliance Inspector)</p>	
<p>6. LICENSEE'S ACKNOWLEDGMENT</p> <p>The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.</p> <p style="text-align: center;">_____ (Date)</p> <p style="text-align: right;">_____ (Licensee Representative - Title or Position)</p>	

COPIES: ☐ LICENSEE ☐ COMPLIANCE REGION ☒ DIV. OF ST. & LIC. REL. ☐ DIV. OF COMPLIANCE

9302170121 921007  
PDR FOIA  
KEPPLER92-446 PDR

*2/17/121*

*A/39*