

04001341271E

40-1341

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1630 Chestnut Street Tower II

RETURN ORIGINAL TO PDR, HQ.


June 28, 1985

Mr. R. Dale Smith
U.S. Nuclear Regulatory Commission
Uranium Recovery Field Office
P.O. Box 25325
Denver, Colorado 80225

Dear Mr. Smith:

In the Matter of
Tennessee Valley Authority

) Docket No. 40-1341
)



The May 31, 1985 letter from Edward F. Hawkins of NRC to TVA expressed concern in regard to the quality control program for riprap associated with the Edgemont decommissioning project. The letter stated that TVA's quality control program is insufficient to ensure that the riprap gradation meets the design specifications and requested TVA submit a riprap gradation quality control program.

The enclosed information provides TVA's riprap gradation quality control program for your review and approval.

If you have any questions or comments concerning this matter, please get in touch with W. M. Belvin of my staff at FTS 858-2693 in Chattanooga.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. W. Hufham
by *RHL*
J. W. Hufham, Manager
Licensing and Risk Protection

Enclosure

8507240033 850628
PDR ADDCK 04001341
C PDR

DECLASSIFIED ORIGINAL

Certified By Mary C. Hood

FEE EXEMPT

Enclosure

EDGEMONT DECOMMISSION PROJECT
QUALITY CONTROL PROGRAM FOR GRADATION OF RIPRAP

Inspectors from Silver King Mines, Inc. (SKM), shall perform weekly random quarry inspections at the quarry of the successful riprap bidder. The SKM inspector will verify at the quarry that the riprap meets the specifications stated in Section 5.5.5 of MacLaren Report No. 10. Materials not meeting the specifications will be rejected at the quarry. Inspections will continue until the deficiency is corrected and the riprap produced meets the specification of Section 5.5.5. TVA will verify that this program is implemented through inspections and examinations of documentation.