

ENCLOSURE 1

NOTICE OF VIOLATION

Alabama Power Company  
Farley Unit 1

Docket No. 50-348  
License No. NPF-2

The following violation was identified during an inspection conducted on May 11 - June 10, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1 requires that procedures shall be established, implemented, and maintained. Administrative Procedure 35, "General Plant Housekeeping and Cleanliness Control" requires in Section 5.1.9 that flammable liquids will not be stored or left unattended in the auxiliary building, diesel generator building and service water structure at any time.

Contrary to the above, on May 22, 1985, combustible liquids were found unattended in the hot machine shop located in the auxiliary building.

This is a Severity Level V violation (Supplement 1).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JUN 24 1985

8507110227 850624  
PDR ADOCK 05000348  
G PDR