

MAY 21 1985

Docket No. 50-87

Westinghouse Electric Corporation
ATTN: Mr. G. W. Scholand, Manager
Westinghouse Nuclear
Training Center
505 Shiloh Boulevard
Zion, IL 60099

Gentlemen:

This refers to the routine physical security inspection conducted by Messrs. G. L. Pirtle and B. Drouin of this office on April 8-15, 1985, of activities at the Westinghouse Training Reactor authorized by NRC License No. R-119, and to the discussion of our findings with Mr. G. W. Scholand and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements. You will be notified by separate correspondence of our decision regarding enforcement actions based on the findings of this inspection. No written response is required until you are notified of the proposed enforcement action.

A concern exists pertaining to the management's direction and oversight of the security program which warrants senior management involvement. Specifics of this concern are addressed in Paragraph 4.e of the Report Details. Actions to resolve this concern will be reviewed during future inspections.

Certain commitments to resolve concerns noted during the inspection are identified in paragraphs 4.a(1) and (2), 4.c, and 4.d. Please advise us if our understanding of these commitments is incorrect.

An enforcement conference was held on May 3, 1985. Details of this meeting are addressed in Paragraph 5 of the inspection report.

Areas examined during the inspection concern a subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Consequently, our report of this inspection will not be placed in the Public Document Room.

IE02
11


8505310296 850521
PDR ADOCK 05000087
G PDR

ATTACHMENT CONTAINS
TO CFR 2.790(d) INFO

MAY 21 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



J. A. Hind, Director
Division of Radiation Safety
and Safeguards

Enclosure: Inspection Report
No. 50-087/85001(DRSS)
(PART 2.790(d) INFORMATION)


cc w/encl:

C. Bach, Manager Instruction
(Fundamentals) and Training
Reactor
A. T. Sabo, Director, Licensing
Safeguards & Safety
A. Joseph Nardi, Manager
NES License Administration
DMB/Document Control Desk (RIDS)


RIII


Pirtle/kja
05/21/85


RIII


Drouin

RIII


Creed


RIII


Ridgway
5/21/85


RIII


Axelsson
5/21/85

RIII


Stapleton
5/21/85

RIII


Hind
5/21/85

ATTACHMENT CONTAINS
10 CFR 2.790(d) INFO