

CORRECTED COPY

MATERIALS LICENSE

Amendment No. 06

Pursuant to the Atomic Energy Act of 1954, as amended, the Energy Reorganization Act of 1974 (Public Law 93-438), and Title 10, Code of Federal Regulations, Chapter I, Parts 30, 31, 32, 33, 34, 35, 36, 39, 40, and 70, and in reliance on statements and representations heretofore made by the licensee, a license is hereby issued authorizing the licensee to receive, acquire, possess, and transfer byproduct, source, and special nuclear material designated below; to use such material for the purpose(s) and at the place(s) designated below; to deliver or transfer such material to persons authorized to receive it in accordance with the regulations of the applicable Part(s). This license shall be deemed to contain the conditions specified in Section 183 of the Atomic Energy Act of 1954, as amended, and is subject to all applicable rules, regulations, and orders of the Nuclear Regulatory Commission now or hereafter in effect and to any conditions specified below.

OFFICIAL RECORD COPY

Licensee		In accordance with the letter dated March 21, 1996,
1. Gillett Cardiovascular Laboratory P.C.		3. License Number 06-27909-01 is amended in its entirety to read as follows:
2. 21 Woodland Street, Suite 110 Hartford, Connecticut 06105		4. Expiration Date April 30, 2002
		5. Docket or Reference No. 030-29568
6. Byproduct, Source, and/or Special Nuclear Material	7. Chemical and/or Physical Form	8. Maximum Amount that Licensee May Possess at Any One Time Under This License
A. Any byproduct material identified in 10 CFR 35.100	A. Any radiopharmaceutical identified in 10 CFR 35.100	A. As needed
B. Any byproduct material identified in 10 CFR 35.200	B. Any radiopharmaceutical identified in 10 CFR 35.200 except generators and gas	B. As needed
9. Authorized Use		
A. Any uptake, dilution and excretion procedure approved in 10 CFR 35.100.		
B. Any imaging and localization procedure approved in 10 CFR 35.200.		

CONDITIONS

10. Licensed material may be used only at the licensee's facilities located at 21 Woodland Street, Suite 110, Hartford, Connecticut.
11. The Radiation Safety Officer for this license is John I. Baron, M.D.
12. Licensed material listed in Item 6 above is only authorized for use by, or under the supervision of, the following individuals for the materials and uses indicated:

Authorized UsersMaterial and Use

Thomas D. Springer, M.D.

35.100; 35.200

Brian J. Grogan, M.D.

35.100; 35.200

Steven R. Urbanski, M.D.

35.100; 35.200

Nicholas R. Salerno, M.D.

35.100; 35.200

9610150057 960806
PDR ADOCK 03029568
C PDR

ML 10

MATERIALS LICENSE
SUPPLEMENTARY SHEET

License Number

06-27909-01

Docket or Reference Number

030-29568

CORRECTED COPY

Amendment No. 06

Gerard C. Buffo, M.D. 35.100; 35.200

Bruce P. Arose, M.D. 35.100; 35.200

Todd M. Talmadge, M.D. 35.100; 35.200

John I. Baron, M.D. 35.100; 35.200

13. In addition to the possession limits in Item 8, the licensee shall further restrict the possession of licensed material so that at no time is a quantity of radioactive material possessed in excess of a quantity which requires decommissioning funding in accordance with 10 CFR 30.35(d), 10 CFR 40.36(b) or 10 CFR 70.25(d).
14. The licensee is authorized to transport licensed material in accordance with the provisions of 10 CFR Part 71, "Packaging and Transportation of Radioactive Material."
15. Except as specifically provided otherwise in this license, the licensee shall conduct its program in accordance with the statements, representations, and procedures contained in the documents, including any enclosures, listed below. The Nuclear Regulatory Commission's regulations shall govern unless the statements, representations and procedures in the licensee's application and correspondence are more restrictive than the regulations.
- A. Application dated December 27, 1991
 - B. Letter dated April 2, 1992
 - C. Letter dated May 5, 1992
 - D. Letter dated March 21, 1996

For the U.S. Nuclear Regulatory Commission

Original Signed By:

John D. Kinneman

By

Nuclear Materials Safety Branch
Region I

King of Prussia, Pennsylvania 19406

Date

AUG - 6 1996

AUG - 6 1996

Arthur B. Landry, Jr., M.D.
President
Gillett Cardiovascular Laboratory P.C.
21 Woodland Street, Suite 110
Hartford, CT 06105

Dear Dr. Landry:

This refers to your letter dated July 15, 1996, requesting an amendment to your "C" license. During a review of this request, it was noted that when we processed your request to change the name of your facility (Amendment No. 06), the address listed on your license was also changed by mistake. Please be advised that an amendment to your license is not needed to correct this error. A Corrected Copy of Amendment No. 06 to your License No. 06-27909-01 is enclosed.

We apologize for any inconvenience this error may have caused.

Sincerely,

ORIGINAL SIGNED BY:

John D. Kinneman, Chief
Nuclear Materials Safety Branch 2
Division of Nuclear Materials Safety

License No. 06-27909-01
Docket No. 030-29568
Control No. 123058

Enclosure:
Corrected Copy of Amendment No. 06

DOCUMENT NAME: R:\WPS\MLTR\L0627909.01X

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	N	DNMS/RI	N				
NAME	SLodhi		JKinneman					
DATE	08/01/96		08/2/96		08/ /96		08/ /96	

MNSB TELEPHONE CONVERSATION RECORD

Person Calling: Sattar Lodhi
8901

Phone No.: (203) 525

Person Called: Dr. Arthur Landry

Date: August 1, 1996

Facility Name: Gillett Cardiovascular Laboratory P. Time: 10:45 a.m.
Hartford CT

License No. 06-29709-01

Docket No. 030-29568

Subject: Verification of address of use


Summary: I called Dr. Landry to confirm that the address of use as well as the mailing address on the license is to be changed to 21 Woodland Street, Suite 110, Hartford, CT

Dr. Landry was on vacation and I talked to Dr. John Baron, who is the RSO. He stated that:

1. both the mailing address and the address of use has been 21 Woodland street for over 5 years;
2. during the last amendment the address was changed by mistake;
3. he contacted Michele Beardsley about this and was told that they need to submit an amendment request;

The last amendment request did not include a change of address (only a change of name & RSO). It looks like they need a corrected copy and not amended license.

Action Required/Taken: Discuss with John

Signature: 

Mail Control Number: 123507

**GILLETT CARDIOVASCULAR LABORATORY P.C.
21 WOODLAND STREET, SUITE 110
HARTFORD, CT. 06105**

July 15, 1996

030 - 29568

Ms Michele Beardsley
Nuclear Regulatory Commission
Region I
Nuclear Material Section B
475 Allendale Road
King of Prussia, PA 19406-1415


REFERENCE: License no. : 06-27909-01

Dear Ms. Beardsley:

Please amend the above license to correct the address of our facility. The address was previously, and remains 21 Woodland Street, Suite 110, Hartford, Ct 06105.

A check for the license amendment fee in the amount of \$440 is enclosed. Please let me know if you require additional information. Thank you.

Sincerely,



Arthur B. Landry, Jr. MD
President

OFFICIAL RECORD COPY

ML 10

123507

JUL 29 1996

LICENSE FEE REQUIREMENTS

LICENSE FEE AND DEBT COLLECTION BRANCH
DIVISION OF ACCOUNTING AND FINANCE
OFFICE OF THE CONTROLLER
U.S. NUCLEAR REGULATORY COMMISSION
WASHINGTON, DC 20555-0001GILLET CARDIOVASCULAR LABORATORY, P.C.
ATTN: ARTHUR B. LANDRY, JR., MD
PRESIDENT
21 WOODLAND STREET
SUITE 110
HARTFORD, CT 06105

TYPE OF ACTION

- ☐
- NEW LICENSE
-
- ☐
- RENEWAL OF LICENSE
-
- ☐
- AMENDMENT TO LICENSE

REQUESTED DATE

7-15-96

LICENSE NUMBER

06-27909-01

CONTROL NUMBER

123507

*THE LICENSING STAFF HAS INFORMED US THAT NO AMENDMENT
TO THE LICENSE IS NECESSARY.

I. APPLICATION FEE DUE

Your request for a licensing action is subject to the fee(s) in the category(ies) noted below in accordance with Section 170.31 of the enclosed Federal Register notice. Payment of the fee is required prior to the issuance of the license, renewal, or amendment.

FEE CATEGORY	APPLICATION	RENEWAL	AMENDMENT
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$

FEE(s) DUE \$
PAYMENT RECEIVED \$
AMOUNT DUE \$

- ☐ Your request was received without the prescribed application fee.
- ☐ We received your Check No. _____ in the amount of \$ _____. Payment of the additional fee noted above is required.
- ☐ Your request will increase the scope of your license program. Therefore, your request is subject to the application fee(s) noted above. Refer to Section 170.31 and Footnote 1(d)(2).
- ☐ Your license expired prior to the receipt of your application for renewal. Therefore, your request is subject to the application fee(s) noted above. Refer to Section 170.31 and Footnote 1(a).

MAKE PAYMENT OF THE FEE(S) TO THE U.S. NUCLEAR
REGULATORY COMMISSION AND MAIL THE PAYMENT TO THE
ADDRESS LISTED AT THE TOP OF THIS FORM. IF WE DO NOT
RECEIVE A REPLY FROM YOU WITHIN 30 CALENDAR DAYS FROM
THE DATE LISTED BELOW, WE SHALL ASSUME THAT YOU DO NOT
WISH TO PURSUE YOUR APPLICATION AND WILL VOID THIS
ACTION.

II. FEE NOT REQUIRED

- ☒ Enclosed is Check No. 5572 ⁵⁸⁴⁴⁰ which accompanied your request. The fee is not required because: *
- ☐ We received your Check No. _____ in payment of the fee.
- ☐ The Licensing staff has informed us that your request is to be considered as a continuation of your request dated _____, Control No. _____.
- ☐ Your request was combined, prior to review, with your request, Control No. _____.

III. CHECK RETURNED

- ☐ Enclosed is Check No. _____ which was returned to us by the bank for:
- ☐ INSUFFICIENT FUNDS
- ☐ ACCOUNT CLOSED
- ☐ OTHER

MAIL THE REPLACEMENT CHECK TO THE ADDRESS LISTED AT THE
TOP OF THIS FORM AND REFERENCE THE ABOVE CONTROL
NUMBER.

IV. LICENSE ISSUED WITHOUT THE REQUIRED FEE

- ☐ License No. _____ Amendment No. _____ issued on _____ was issued without the required fee being collected. The fee required is noted in Section I of this form.
- ☐ The scope of your licensed program was increased. Therefore, your request is subject to the application fee(s) noted in Section 1 of this form. Refer to Section 170.31 and Footnote 1(d)(2).
- ☐ Because of the urgency of your request, the license was issued without remittance of the prescribed fee noted in Section 1 of this form.

SIGNATURE - LICENSE FEE ANALYST

BRENDA BROWN

LFDCB

BB *BB*
8/6/96

LFDCB

Distribution:

MAF Correspondence FY

LFDCB Chief

Invoice File w/encl

License Fee

LFDCB Analyst

LFDCB R/F *(2)*

DAF R/F

DATE

OC/DAF/SP (LF-3-2-7)
8-6-96

BETWEEN:

LICENSE FEE MANAGEMENT BRANCH, ARM
AND
REGIONAL LICENSING SECTIONS

(FOR LFMS USE)
INFORMATION FROM LTS

PROGRAM CODE: 02200
STATUS CODE: 0
FEE CATEGORY: 7C
EXP. DATE: 20020430
FEE COMMENTS: -----
DECOM FIN ASSUR REQD: N

LICENSE FEE TRANSMITTAL

A. REGION

I

1. APPLICATION ATTACHED

APPLICANT/LICENSEE: GILLET CARDIOVASCULAR LAB. P.C.

RECEIVED DATE: 960729

DOCKET NO: 3029568

CONTROL NO.: 123507

LICENSE NO.: 06-27909-01

ACTION TYPE: AMENDMENT

2. FEE ATTACHED

AMOUNT: ~~440.00~~

CHECK NO.: ~~5572~~

3. COMMENTS

SIGNED
DATE

M. A. Perkins
7/31/96

B. LICENSE FEE MANAGEMENT BRANCH (CHECK WHEN MILESTONE 03 IS ENTERED) *1*

1. FEE CATEGORY AND AMOUNT: -----

2. CORRECT FEE PAID- APPLICATION MAY BE PROCESSED FOR:

AMENDMENT -----

RENEWAL -----

LICENSE -----

3. OTHER -----

SIGNED
DATE

8/5/96
Per Rebecca Brown
to KI
for voiding
Error made.
To be done as
a corrected copy

As

1976 AUG - 2 MILEST

Log	<i>Aug 6</i>
Check No.	<i>5572</i>
Amount	<i>440</i>
FEE CATEGORY	<i>7C</i>
DATE	<i>8/6/96</i>
BY	<i>BB</i>

check RETURNED TO
LICENSEE Action TO
BE VOIDED

VOID SHEET

030 29568

TO: License Fee Management Branch

FROM: RI

SUBJECT: VOIDED APPLICATION

Aug 6 123507 ✓

Control Number: 123507

Applicant: Gillet Cardiovascular Lab., P.C.

Date Voided: 8-6-96

Reason for Void: Original change of Licensee's
address was an error. No work done on
Amendment. A Corrected Copy of Amend-
ment #06 will be issued. 06-27909-01

Rebecca J. Brown 8/6/96
Signature Date

Attachment:
Official Record Copy of
Voided Action

FOR LFMB USE ONLY

Final Review of VOID Completed:

Refund Authorized and processed

No Refund Due

Fee Exempt or Fee Not Required

Comments: check returned to
licensee on 8/6/96

Log completed

Processed by: AB

OFFICIAL RECORD COPY ML 10