

file

JUN 12 1985

Brinton C. Donalson, D.O.
609 East Jolly Road
Lansing, MI 48910

Dear Dr. Donalson:

We are in receipt of your letter dated May 29, 1985 containing the results of the close-out survey of your nuclear medicine facilities. Please be advised, however, that survey measurements must be made with an instrument that has been properly calibrated within a 12 month period preceeding the date of the survey. Your Picker survey meter was last calibrated on August 18, 1983, a time period in excess of the required frequency.

Please resubmit your close-out survey with measurements made by an instrument that has been calibrated within the previous twelve months. Include the manufacturer's name and model number of the instrument, background readings and the last calibration date. Please also inform us of the name of the organization or person who performed the calibration.

We are returning a copy of your submittal to aid you in this effort. We are also returning your NRC Form 314 which requires your signature under "Certifying Official". Please include this document with your survey report.

You should reply in duplicate within 30 days referencing Control No. 78643. If you have questions or require additional information you may contact me on (312) 790-5625.

Sincerely,

Original Signed By
B.J. Holt
Materials Licensing Section

Enclosure: Letter dated May 29, 1985
with attachments

8507260033 850708
REG3 LIC30
21-15508-01 PDR

RIII

Holt/cm
06/05/85

6/12/85